

City of Cockburn Asbestos Register																		
Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liabile to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
18/11/2019	Tempest Park Pavilion (Tom Greengrass Pavilion) - Cnr Stephano Way & Prospero Crescent, Coolbellup WA 6163	Coolbellup	122	2038	Kitchen - Electrical switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Tempest Park Pavilion (Tom Greengrass Pavilion) - Cnr Stephano Way & Prospero Crescent, Coolbellup WA 6163	Coolbellup	122	2038	Bar Store Room - Tiling grout	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Tempest Park Pavilion (Tom Greengrass Pavilion) - Cnr Stephano Way & Prospero Crescent, Coolbellup WA 6163	Coolbellup	122	2038	Football Home Room Toilet/Bathroom - Tiling grout	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Tempest Park Pavilion (Tom Greengrass Pavilion) - Cnr Stephano Way & Prospero Crescent, Coolbellup WA 6163	Coolbellup	122	2038	Cricket Home Room Toilet/Bathroom - Tiling grout	10	YES	Intact, not friable	Yes	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Tempest Park Pavilion (Tom Greengrass Pavilion) - Cnr Stephano Way & Prospero Crescent, Coolbellup WA 6163	Coolbellup	122	2038	Men's External Toilet - Tiling grout	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Jean Willis House - Administration & Daycare Respite Centre, 249 Healy Road, Hamilton Hill WA 6163	Hamilton Hill	20	2045	Kitchen - Sink black tar resin sound dampener	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Jean Willis House - Administration & Daycare Respite Centre, 249 Healy Road, Hamilton Hill WA 6163	Hamilton Hill	20	2045	Female Toilet - Tile & grout under lino	10	YES	Intact, not friable	No, if undisturbed	LOW	Encapsulated under newly laid lino.	Unknown if tile or grout contain ACM, assumed due to age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Jean Willis House - Administration & Daycare Respite Centre, 249 Healy Road, Hamilton Hill WA 6163	Hamilton Hill	20	2045	Male Toilet - tile & grout under lino	10	YES	Intact, not friable	No, if undisturbed	LOW	Encapsulated under newly laid lino.	Unknown if tile or grout contain ACM, assumed due to age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
18/11/2019	Jean Willis House - Administration & Daycare Respite Centre, 249 Healy Road, Hamilton Hill WA 6163	Hamilton Hill	20	2045	Fencing - car park	65	YES	Damaged and deteriorating	Yes	MODERATE	Replace damaged fencing with non ACM product. Ensure vegetation is kept away from fencing to prevent panels becoming friable	City should liaise with the neighbouring property to ensure control measures are effectively implemented. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Enright Reserve Changerooms, 221 Enright Reserve, Hamilton Hill WA 6163	Hamilton Hill	124	2044	Female Toilet - tile grout	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Enright Reserve Changerooms, 221 Enright Reserve, Hamilton Hill WA 6163	Hamilton Hill	124	2044	Male Toilet - tile grout	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Enright Reserve Changerooms, 221 Enright Reserve, Hamilton Hill WA 6163	Hamilton Hill	124	2044	Disabled Public Toilets - tile grout	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Enright Reserve Changerooms, 221 Enright Reserve, Hamilton Hill WA 6163	Hamilton Hill	124	2044	Male Public Toilet - tile grout	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Enright Reserve Changerooms, 221 Enright Reserve, Hamilton Hill WA 6163	Hamilton Hill	124	2044	Female Public Toilet - tile grout	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Wally Hagan Stadium, Starling Street, Hamilton Hill WA 6963	Hamilton Hill	7	128	Electrical switchboard & fuses	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Wally Hagan Stadium, Starling Street, Hamilton Hill WA 6963	Hamilton Hill	7	128	Club Room Bar/Kitchen - sink black tar resin sound dampener	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Davilak Clubrooms (Davilak Reserve), Lucius Road, Hamilton Hill WA 6163	Hamilton Hill	119	2002	Female Toilets - tile grout	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
18/11/2019	Davilak Clubrooms (Davilak Reserve), Lucius Road, Hamilton Hill WA 6163	Hamilton Hill	119	2002	Male Toilet - tile grout	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Davilak Clubrooms (Davilak Reserve), Lucius Road, Hamilton Hill WA 6163	Hamilton Hill	119	2002	Male Public Toilet - tile grout	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Davilak Clubrooms (Davilak Reserve), Lucius Road, Hamilton Hill WA 6163	Hamilton Hill	119	2002	Disabled Public Toilets - tile grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Davilak Clubrooms (Davilak Reserve), Lucius Road, Hamilton Hill WA 6163	Hamilton Hill	119	2002	Female Public Toilet - tile grout	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18/11/2019	Pump House (Davilak Reserve), Lucius Road, Hamilton Hill WA 6163	Hamilton Hill	118	2001	Pump House - electrical switchboard & fuses	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label to be implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Meerilinga Childcare Centre, 219 Winterfold Road, Coolbellup WA 6163	Coolbellup	49	4354	Playroom Early Learning - ceiling to sliding door main entry	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building and characteristics. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Meerilinga Childcare Centre, 219 Winterfold Road, Coolbellup WA 6163	Coolbellup	49	4354	Playroom - ceiling to sliding door entry	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building and characteristics. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Meerilinga Childcare Centre, 219 Winterfold Road, Coolbellup WA 6163	Coolbellup	49	4354	Office - Extension ceiling	6	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building and characteristics. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Meerilinga Childcare Centre, 219 Winterfold Road, Coolbellup WA 6163	Coolbellup	49	4354	Toy Library - ceiling to sliding door	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building and characteristics. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
22/11/2019	Meerlinga Childcare Centre, 219 Winterfold Road, Coolbellup WA 6163	Coolbellup	49	4354	Eaves	40	YES	Intact, not friable	Yes	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building and characteristics. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Meerlinga Childcare Centre, 219 Winterfold Road, Coolbellup WA 6163	Coolbellup	49	4354	Electrical switchboard	0.5	YES	Damaged, not friable	Yes	LOW	Seal damaged edges or replace with non ACM product. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Meerlinga Childcare Centre, 219 Winterfold Road, Coolbellup WA 6163	Coolbellup	49	4354	Community Training Room - ceiling to sliding door	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required before disturbed, ACM suspected due to the age of the building and characteristics. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Entrance/Exit - ceiling panels to front/lean-to	50	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Activity Room West - vinyl tile	100	YES	Damaged and deteriorating	Yes	MODERATE	Seal or replace damaged tiles with non-ACM product	Testing required. Caution label implemented	Yes, before disturbed	No Testing conducted previously negative result achieved, awaiting confirmation from the City	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Toilet/Laundry West & East - tile grout	70	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Kitchen/Office - vinyl flooring	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required. Caution label implemented	Yes, before disturbed	No - Testing conducted previously negative result achieved, awaiting confirmation from the City	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Kitchen - Sink tar resin sound dampener	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	West Office - panels below windows	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	No	Yes - BA7172/02 - Chrysotile Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Activity Room West - ceiling panels & fascia boards	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Kitchen - ceiling panels	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Office next to Kitchen - ceiling panels	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Toilet/Laundry West & East - ceiling panels	80	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Activity Room East - vinyl tiles	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required. Caution label implemented	Yes, before disturbed	No - Testing conducted previously negative result achieved, awaiting confirmation from the City	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Activity Room East - ceiling panels & fascia boards	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Activity Room East - children sink lining	1	YES	Damaged, not friable	Yes	LOW	Remove and replace with non ACM product	Testing required. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Activity Room East - panels below windows	8	YES	Damaged and deteriorating	Yes	MODERATE	Remove damaged panel and replace with non ACM product. Curtain has been contaminated with ACM fibres and should be removed as controlled ACM waste	Caution label implemented	Yes, before disturbed	Yes - BA7172/02 - Chrysotile Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	East Office - ceiling	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	East Office - gable panels	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Activity Storeroom East - ceiling panels	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	West Office - gable panels	2	YES	N/A	N/A	N/A	Testing required	Non suspected	No	Yes - BA7156/01 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	West Office - ceiling panels	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	East Store Room - vinyl flooring	100	YES	Damaged and deteriorating	Yes	MODERATE	Monitor for wear and damages	Cracked and damaged tiles to doorway between Activity Room East and East Room	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	East Store Room Kitchen - sink, black tar resin sound dampener	2	YES	Intact, not friable	Yes	LOW	Encapsulate to prevent damage when storing items.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Gas Heater - gaskets and lining	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Encapsulated, assumed intact. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	East Store Room - ceiling and fascia	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	East Store Room Toilet - tile grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label to be implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Pineview Community Health Centre, 30 Mopsa Way, Coolbellup WA 6163	Coolbellup	14	2129	Exterior Garage - guttering	4	YES	Intact, not friable	Yes	MODERATE	Remove and replace with non ACM product.	Unknown if internal guttering is sealed, fibres can be damaged from the removal and disturbance of tree debris. Tree debris could be friable. Caution label to be implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18-Nov-19	Cockburn Tennis Club, 17A Recreation Road (11 Lucius Road), Hamilton Hill WA 6163	Hamilton Hill	45	2004	Window Putty	5	YES	Intact, not friable	No, if undisturbed	LOW	Repaint/seal any deteriorated areas to contain ACM. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Ethel Cooper Kindergarten, 34 Ingram Street, Hamilton Hill WA 6163	Hamilton Hill	13	2041	Kitchen - sink, black tar resin sound dampener	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Ethel Cooper Kindergarten, 34 Ingram Street, Hamilton Hill WA 6163	Hamilton Hill	13	2041	Play Room - sink (kids), black tar resin sound dampener	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Cockburn Senior Citizens Association, 9 Young Place (Clara Road), Hamilton Hill WA 6163	Hamilton Hill	16	113	Fencing and ridge capping next to carpark	50	YES	Damaged and deteriorating	Yes	HIGH	Remove ACM fencing and ridge capping and replace with non ACM product. Cut back vegetation from fencing to prevent ACM from being friable.	Vegetation causing panels and ridge capping to be friable. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Cockburn Senior Citizens Association, 9 Young Place (Clara Road), Hamilton Hill WA 6163	Hamilton Hill	16	113	Fencing and ridge capping next to driveway	120	YES	Damaged and deteriorating	Yes	HIGH	Remove ACM fencing and replace with non ACM product. Cut back vegetation from fencing to prevent ACM from being friable.	Vegetation causing panels and ridge capping to be friable. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Cockburn Senior Citizens Association, 9 Young Place (Clara Road), Hamilton Hill WA 6163	Hamilton Hill	16	113	Eaves	65	YES	Intact, not friable	No, if undisturbed	LOW	Seal damaged panel around copper pipe. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
19/11/2019	Cockburn Senior Citizens Association, 9 Young Place (Clara Road), Hamilton Hill WA 6163	Hamilton Hill	16	113	Kitchen - benches & draining board, black tar resin sound dampener	20	YES	Intact, not friable	No, if undisturbed	LOW	Encapsulate to prevent damage when storing items.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Cockburn Senior Citizens Association, 9 Young Place (Clara Road), Hamilton Hill WA 6163	Hamilton Hill	16	113	Pantry - ceiling panels	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Cockburn Senior Citizens Association, 9 Young Place (Clara Road), Hamilton Hill WA 6163	Hamilton Hill	16	113	Female Toilet - tile grout	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Cockburn Senior Citizens Association, 9 Young Place (Clara Road), Hamilton Hill WA 6163	Hamilton Hill	16	113	Male Toilet - tile grout	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18-Nov-19	Southwell Community Centre (Second Harvest), 8 Caffery Place, Hamilton Hill WA 6163	Hamilton Hill	41	148	Kitchen - sink, black tar resin sound dampener	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18-Nov-19	Southwell Community Centre (Second Harvest), 8 Caffery Place, Hamilton Hill WA 6163	Hamilton Hill	41	148	Kitchen - tile grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18-Nov-19	Southwell Community Centre (Second Harvest), 8 Caffery Place, Hamilton Hill WA 6163	Hamilton Hill	41	148	Store Kitchen - tile grout	7	YES	Damaged, not friable	Yes	LOW	Seal/repair damaged tiles. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18-Nov-19	Goodchild Park Clubrooms, 30 Plantagenet Crescent (Ely Street), Hamilton Hill WA 6163	Hamilton Hill	127	2113	Male Toilet/Bathroom - tile grout	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18-Nov-19	Goodchild Park Clubrooms, 30 Plantagenet Crescent (Ely Street), Hamilton Hill WA 6163	Hamilton Hill	127	2113	Men's Away Change Room - tile grout	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
18-Nov-19	Goodchild Park Clubrooms, 30 Plantagenet Crescent (Ely Street), Hamilton Hill WA 6163	Hamilton Hill	127	2113	Ladies Toilet - tile grout	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Homestead Museum, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	51	133	Windows - putty, all windows	10	YES	Damaged and deteriorating	Yes	HIGH	Remove or seal damaged ACM with non ACM product.	Window putty accessible by visitors. Caution label to be implemented	No	Yes - BA6933/01 - Chrysotile Asbestos Detected	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
19-Nov-19	Azelia Ley - Homestead Museum, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	51	133	Store Room - ceiling panels	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Homestead Museum, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	51	133	Bathroom - panel around the bath	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Homestead Museum, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	51	133	Bathroom - Vinyl flooring under cupboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Homestead Museum, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	51	133	Bathroom - Vinyl flooring, top cover	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Homestead Museum, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	51	133	Kitchen - baby chair covering	1	YES	N/A	N/A	N/A	Testing conducted	Non suspected	No	Yes - BA7036/02 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Homestead Museum, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	88	4369	Chicken Incubator - flue lagging & internal lining	1	YES	Damaged and deteriorating	Yes	HIGH	Remove or seal ACM with non ACM product.	Chicken incubator accessible by visitors. Caution label to be implemented	No	Yes - BA7036/01 - Chrysotile Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
28-Nov-19	Azelia Ley - Dwelling, 97 Davilak Avenue, Hamilton Hill WA 6163	Hamilton Hill	18	131	Kitchen & Hallway (Bedrooms & Lounge) - lino, encapsulated under top lino and carpet	60	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28-Nov-19	Azelia Ley - Dwelling, 97 Davilak Avenue, Hamilton Hill WA 6163	Hamilton Hill	18	131	Laundry & Toilet - tile grout	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28-Nov-19	Azelia Ley - Dwelling, 97 Davilak Avenue, Hamilton Hill WA 6163	Hamilton Hill	18	131	Bathroom Flooring - possible tile grout encapsulated underneath top tiles	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28-Nov-19	Azelia Ley - Dwelling, 97 Davilak Avenue, Hamilton Hill WA 6163	Hamilton Hill	18	131	Eaves	60	YES	Intact, not friable	Yes	LOW	Remove vegetation from eaves, repaint and reseal to contain ACM.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28-Nov-19	Azelia Ley - Dwelling, 97 Davilak Avenue, Hamilton Hill WA 6163	Hamilton Hill	18	131	Electrical switchboard & fuses	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26-Nov-19	Bibra Lake Community Centre, 132 Parkway Road, Bibra Lake WA 6163	Bibra Lake	31	161	Electrical switchboard	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		



Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
26-Nov-19	Bibra Lake Community Centre, 132 Parkway Road, Bibra Lake WA 6163	Bibra Lake	31	161	Reticulation electrical switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26-Nov-19	Bibra Lake Community Centre, 132 Parkway Road, Bibra Lake WA 6163	Bibra Lake	31	161	Main Hall - ACM vinyl flooring tile	120	YES	Damaged and deteriorating	Yes	LOW	Seal edges to entrance doorway and window. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Depot - WorkShop Male Toilets, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	52	152	Workshop Male Toilet - tile grout	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - WorkShop Female Toilets, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	52	152	Workshop Female Toilet - tile grout	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Stephen Smith		
26-Nov-19	Native Arc Training Room - Demountable, 172 Hope Road, Bibra Lake WA 6163	Bibra Lake	36	2518	Eaves	30	YES	Intact, not friable	No, if undisturbed	LOW	Paint to seal otherwise remove and replace with non ACM product.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26-Nov-19	Native Arc Main Building, 172 Hope Road, Bibra Lake WA 6163	Bibra Lake	35	2517	Eaves & Batons	100	YES	Intact, not friable	Yes	LOW	Deterioration occurring in some areas otherwise monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26-Nov-19	Native Arc Main Building, 172 Hope Road, Bibra Lake WA 6163	Bibra Lake	35	2517	Electrical switchboard	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26-Nov-19	Native Arc Main Building, 172 Hope Road, Bibra Lake WA 6163	Bibra Lake	35	2517	Bathroom/ Chemical Store - vanity unit, possible panels behind	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26-Nov-19	Native Arc Main Building, 172 Hope Road, Bibra Lake WA 6163	Bibra Lake	35	2517	Laundry Cupboard - lining to top of cupboard	1	YES	Intact, not friable	Yes	LOW	Seal, encapsulate or do not store items on top shelf where unsealed ACM will become friable	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26-Nov-19	Native Arc Main Building, 172 Hope Road, Bibra Lake WA 6163	Bibra Lake	35	2517	Hallway Linen Cupboard - lining to top of cupboard	1	YES	Intact, not friable	Yes	LOW	Seal, encapsulate or do not store items on top shelf where unsealed ACM will become friable	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26-Nov-19	Native Arc Main Building, 172 Hope Road, Bibra Lake WA 6163	Bibra Lake	35	2517	Kitchen/ICU Hospital - chimney flue lining	4	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Cockburn Wetlands Education Centre, 184 Hope Road, Bibra Lake WA 6163	Bibra Lake	34	2217	Main Hall & North Store Room - vinyl tile flooring	200	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
26/11/2019	Public Toilets Bibra Lake (Round Toilets) West Side, Progress Drive, Bibra Lake WA 6163	Bibra Lake	109	2125	Unisex Disabled, Male, Female Toilet - eaves, ceiling (entire) & batons	120	YES	Damaged and deteriorating	Yes	MODERATE	Reseal peeling paint or remove and replace with non ACM product	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28-Nov-19	South Lakes Out of School Hours Care (South Lake Activity Centre), 62 Mason Court & Elderberry Drive, South Lake WA 6164	South Lake	40	2306	Main Activity Room - gas heater, gaskets & lining	4	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Child Care Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	11	163	Activity Rooms - lino flooring throughout	50	YES	Damaged, not friable	Yes	LOW	Testing required. Seal/encapsulate damaged pieces or remove and replace with non ACM product.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Child Care Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	11	163	Staff Toilet - tile grout	5	YES	Damaged, not friable	Yes	LOW	Testing required. Seal/replace damaged tiles or remove and replace with non ACM product.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Child Care Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	11	163	Laundry - sluice sink, black tar resin underneath	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Child Care Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	11	163	Roof - upper eaves & gable ends	20	YES	Intact, not friable	No, if undisturbed	LOW	Paint to further seal. Monitor for wear and damages	Caution label to be implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Ottey Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	86	175	Cleaners Store - tile grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Ottey Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	86	175	Activity Room 2 - tile grout	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Ottey Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	86	175	Activity Room 1 - tile grout	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Ottey Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	86	175	Unisex Toilet - tile grout	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Ottey Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	86	175	Unisex Toilet (West) - tile grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Ottey Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	86	175	Kitchenette - sink, black tar resin	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Mostly encapsulated. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Ottey Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	86	175	Activity Room 2 - sink, black tar resin	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Mostly encapsulated. Caution label to be implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
28/11/2019	South Lake Ottey Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	86	175	Activity Room 1 - sink, black tar resin	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Presumed as could not gain access. Mostly encapsulated. Caution label to be implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	South Lake Ottey Centre, 2 South Lake Drive, South Lake WA 6164	South Lake	86	175	Electrical switchboard & fuses	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Yangebup Family Centre, 11 Dunraven Drive, Yangebup WA 6164	Yangebup	75	177	Distribution Board No.1 - electrical switchboard & fuses	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Yangebup Family Centre, 11 Dunraven Drive, Yangebup WA 6164	Yangebup	75	177	Distribution Board No.2 - electrical switchboard & fuses	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Female Toilet - tile grout	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Male Toilet - tile grout	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Female Toilet - stall dividers	10	YES	Intact, not friable	No, if undisturbed	LOW	Testing required. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Male Toilet - stall dividers	5	YES	Intact, not friable	No, if undisturbed	LOW	Testing required. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Hall Main Distribution Board - electrical switchboard & fuses	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Change Rooms - tile grout	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Female Exterior Toilets - tile grout	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Umpires Shower Room - tile grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liabile to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Male Disabled Toilet - tile grout	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
21-Nov-19	Yangebup Community Centre, 20 Swallow Drive, Yangebup WA 6164	Yangebup	28	157	Home Team Change Rooms - tile grout	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Old Jandakot Primary School, 12 Poletti Road, Cockburn Central WA 6164	Cockburn Central	37	560	Front Entrance Gable - Shadowline cladding	20	YES	Intact, not friable	Yes	LOW	Repaint/seal any deteriorated areas to contain ACM. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Old Jandakot Primary School, 12 Poletti Road, Cockburn Central WA 6164	Cockburn Central	37	560	Window Putty	30	YES	Damaged and deteriorating	Yes	HIGH	Remove and replace with non ACM product	Window putty in poor condition and breaking down. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Portuguese Cultural Club, 12 Poletti Road, Cockburn Central WA 6164	Cockburn Central	38	586	Electrical switchboard & fuses	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Portuguese Cultural Club, 12 Poletti Road, Cockburn Central WA 6164	Cockburn Central	38	586	Sound Studio - kitchen sink, black tar resin underneath	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Portuguese Cultural Club, 12 Poletti Road, Cockburn Central WA 6164	Cockburn Central	38	586	Eaves (rear)	20	YES	Intact, not friable	No, if undisturbed	LOW	Seal edges to cut out hole. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Navel Base/Shacks - Male Toilet, 1136 Cockburn Road, Henderson WA 6166	Henderson	72	4376	Male Toilet - panel behind cistern	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Navel Base/Shacks - Laundry, 1136 Cockburn Road, Henderson WA 6166	Henderson	71	2018	Laundry - ceiling	40	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Navel Base/Shacks - Laundry, 1136 Cockburn Road, Henderson WA 6166	Henderson	71	2018	Laundry - waste valve/flue	5	YES	Intact, not friable	No, if undisturbed	MODERATE	Repaint Flue to seal ACM. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Navel Base/Shacks - Laundry, 1136 Cockburn Road, Henderson WA 6166	Henderson	71	2018	Gardeners Shed - ceiling	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Navel Base/Shacks - Laundry, 1136 Cockburn Road, Henderson WA 6166	Henderson	71	2018	Electrical switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
22/11/2019	Navel Base/Shacks - North Toilet Block, 1136 Cockburn Road, Henderson WA 6166	Henderson	69	136	Waste valve/flue (internal & external)	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
22/11/2019	Navel Base/Shacks - North Toilet Block, 1136 Cockburn Road, Henderson WA 6166	Henderson	69	136	Plant Room - ceiling	15	YES	Intact, not friable	Yes	MODERATE	Paint to seal otherwise remove and replace with non ACM product.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	Dwelling - 17 (Lot 22) Imlah Court, Jandakot WA 6164	Jandakot	26	3253	Laundry - tiles & grout	10	YES	Damaged and deteriorating	Yes	N/A	Testing conducted	Non suspected	No	Yes - BA7052/01 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
28/11/2019	Dwelling - 17 (Lot 22) Imlah Court, Jandakot WA 6164	Jandakot	26	3253	Toilet - tiles & grout	3	N/A	N/A	N/A	N/A	N/A	Non suspected based on Laundry testing findings	No	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	Dwelling - 17 (Lot 22) Imlah Court, Jandakot WA 6164	Jandakot	26	3253	Bathroom - tiles & grout	10	N/A	N/A	N/A	N/A	N/A	Non suspected based on Laundry testing findings	No	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	Dwelling - 17 (Lot 22) Imlah Court, Jandakot WA 6164	Jandakot	26	3253	Fencing & ridge capping	60	YES	Damaged and deteriorating	Yes	MODERATE	Replace damaged fencing and ridge capping with non ACM product. Ensure vegetation is kept away from fencing to prevent panels becoming friable	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	Dwelling - 17 (Lot 22) Imlah Court, Jandakot WA 6164	Jandakot	26	3253	Laundry - panel below window	2	YES	Damaged, not friable	Yes	MODERATE	Remove and replace with non ACM product	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	Dwelling - 17 (Lot 22) Imlah Court, Jandakot WA 6164	Jandakot	26	3253	Electrical switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Baseball Club (Cockburn City Baseball & Tee Ball Clubrooms), 1 Kent Street, Spearwood WA 6163	Spearwood	112	135	Kiosk floor - vinyl tile	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Baseball Club (Cockburn City Baseball & Tee Ball Clubrooms), 1 Kent Street, Spearwood WA 6163	Spearwood	112	135	Change Rooms - tile grout	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Baseball Club (Cockburn City Baseball & Tee Ball Clubrooms), 1 Kent Street, Spearwood WA 6163	Spearwood	112	135	Laundry Room - sink, black tar resin	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
20/11/2019	Beale Park Baseball Club (Cockburn City Baseball & Tee Ball Clubrooms), 1 Kent Street, Spearwood WA 6163	Spearwood	112	135	Laundry Room - tile grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Baseball Club (Cockburn City Baseball & Tee Ball Clubrooms), 1 Kent Street, Spearwood WA 6163	Spearwood	112	135	Male Public Toilets - tile grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Baseball Club (Cockburn City Baseball & Tee Ball Clubrooms), 1 Kent Street, Spearwood WA 6163	Spearwood	112	135	Female Public Toilets - tile grout	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Clubrooms (Beale Park Soccer Club), 1 Kent Street, Spearwood WA 6163	Spearwood	130	143	Gable ends paneling (and behind Colorbond gable)	15	YES	Damaged, not friable	Yes	MODERATE	Seal damaged edges or replace with non ACM product. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Clubrooms (Beale Park Soccer Club), 1 Kent Street, Spearwood WA 6163	Spearwood	130	143	Electrical Switchboard (South)	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Clubrooms (Beale Park Soccer Club), 1 Kent Street, Spearwood WA 6163	Spearwood	130	143	Electrical Switchboard (Main)	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Clubrooms (Beale Park Soccer Club), 1 Kent Street, Spearwood WA 6163	Spearwood	130	143	Female Toilet - vinyl tile	20	YES	Damaged and friable	Yes	HIGH	Seal vinyl tiles or remove and replace with non ACM product	Caution label implemented	No	Yes - BA7037/02 - Chrysotile Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Clubrooms (Beale Park Soccer Club), 1 Kent Street, Spearwood WA 6163	Spearwood	130	143	Male Toilet - vinyl tile & grout at trough	16	YES	Damaged and friable	Yes	HIGH	Seal vinyl tiles or remove and replace with non ACM product	Caution label implemented	No	Yes - BA7037/02 - Chrysotile Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Beale Park Clubrooms (Beale Park Soccer Club), 1 Kent Street, Spearwood WA 6163	Spearwood	130	143	Physio Room - carpet underlay	15	N/A	Damaged and deteriorating	Yes	N/A	Testing conducted	Non suspected	No	Yes - BA7037/01 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
20/11/2019	Edwardes Park Change Room, 10 Lintott Way, Spearwood WA 6163	Spearwood	116	3209	Eaves	30	YES	Damaged and deteriorating	Yes	MODERATE	Replace damaged panels with non ACM product	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Dwelling - City Caretakers Cottage, 286 Rockingham Road, Spearwood WA 6163	Spearwood	8	139	Kitchen - sink, black tar resin underneath	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Spearwood Library, 286 Rockingham Road (9 Coleville Crescent), Spearwood WA 6163	Spearwood	48	114	Eaves & Facias	400	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Smart Park Toilets, 46 Barrington Street, Spearwood WA 6163	Spearwood	111	162	Male Toilet - tile grout	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Smart Park Toilets, 46 Barrington Street, Spearwood WA 6163	Spearwood	111	162	Male Toilet - sink, black tar resin underneath	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Further seal otherwise monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Smart Park Toilets, 46 Barrington Street, Spearwood WA 6163	Spearwood	111	162	Female Toilet - tile grout	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Smart Park Toilets, 46 Barrington Street, Spearwood WA 6163	Spearwood	111	162	Female Toilet - sink, black tar resin underneath	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Further seal otherwise monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
26/11/2019	Smart Park Toilets, 46 Barrington Street, Spearwood WA 6163	Spearwood	111	162	Fencing	50	YES	Damaged and deteriorating	Yes	MODERATE	Remove and replace all fencing with non ACM product to eliminate the likelihood of ACM disturbed through park maintenance work tasks or general public brushing against unsealed fence. ACM debris to be removed next to 48 Barrington Road fence.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	Dwelling - 83 Hamilton Road, 83 Hamilton Road, Spearwood WA 6163	Spearwood	17	184	Electrical Switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	Dwelling - 83 Hamilton Road, 83 Hamilton Road, Spearwood WA 6163	Spearwood	17	184	Eaves	70	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Some minor pitting to water damaged corners others sealed and intact. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
28/11/2019	Dwelling - 83 Hamilton Road, 83 Hamilton Road, Spearwood WA 6163	Spearwood	17	184	Packers between limestone foundation and wooden support beams	1-100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Unknown quantity and locations. Assumed ACM present due to age construction of the building, high likelihood of presence. Currently encapsulated underneath building.	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
28/11/2019	Dwelling - 83 Hamilton Road, 83 Hamilton Road, Spearwood WA 6163	Spearwood	17	184	Window Putty	30	YES	Damaged and deteriorating	Yes	LOW	Remove ACM or seal laundry window. Monitor for wear and damages	Testing required. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Naval Cadets (Cockburn CVES Building), 13 Kent Street, Spearwood WA 6163	Spearwood	1	156	Fencing & ridge capping	100	YES	Damaged and deteriorating	Yes	MODERATE	Remove and replace damaged panels and ridge capping with non ACM product. Keep vegetation away from fencing to prevent panels becoming friable.	Testing required. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
29/11/2019	Naval Cadets (Cockburn CVES Building), 13 Kent Street, Spearwood WA 6163	Spearwood	1	156	Hallway, Male & Female Toilets - tile grout	35	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Administration Office (Cockburn Civic Centre), 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	9	119	Eaves & Facias	800	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Testing required. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Administration Office (Cockburn Civic Centre), 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	9	119	Window Putty	200	YES	Damaged and deteriorating	Yes	MODERATE	Seal to encapsulate or remove and replace with non ACM product	Window putty in poor condition and breaking down. Caution label implemented	No	Yes - BA7034/02 Chrysotile Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Administration Office (Cockburn Civic Centre), 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	9	119	Render	1000	N/A	Intact, not friable	No, if undisturbed	N/A	Testing conducted	Non suspected	No	Yes - BA7034/01 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Administration Office (Cockburn Civic Centre), 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	9	119	Air Conditioning Plant Room - electrical switchboard & fuses	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Administration Office (Cockburn Civic Centre), 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	9	119	Air Conditioning Plant Ducts - seals	60	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Eaves & Facias	300	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		



Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Popcorn Ceiling Panels	500	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Staff Toilet - tile grout	20	N/A	Intact, not friable	No, if undisturbed	N/A	Testing conducted	Non suspected	No	Yes - BA7035/02 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Female Toilet - tile grout	30	N/A	Intact, not friable	No, if undisturbed	N/A	Testing conducted	Assumed the same as Staff Toilet Testing. Non suspected	No	Yes - BA7035/02 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Male Toilet - tile grout	30	N/A	Intact, not friable	No, if undisturbed	N/A	Testing conducted	Assumed the same as Staff Toilet Testing. Non suspected	No	Yes - BA7035/02 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Electrical Switchboard - door lining	6	YES	Intact, not friable	No, if undisturbed	LOW	Seal or remove and replace with non ACM product. Monitor for wear and damages	Lining is unsealed and can become friable with access. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Electrical Switchboard - Switchboard & Fuses	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Kitchen, Foyer, Dry Store, Office - tile grout	100	YES	Intact, not friable	No, if undisturbed	LOW	Testing required. Seal damaged area. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Kitchenette - sink, black tar resin	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Bar - sink, black tar resin	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Kitchen - sink & benches, black tar resin sound dampener	25	YES	Intact, not friable	No, if undisturbed	LOW	Encapsulate to ensure ACM is not disturbed when items are being stored. Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Cleaners Store & Toilet #1 - tile grout	10	N/A	Intact, not friable	No, if undisturbed	N/A	Testing conducted	Assumed the same as Staff Toilet Testing. Non suspected	No	Yes - BA7035/02 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
25/11/2019	Cockburn Senior Centre, 9 Coleville Crescent (300 Rockingham Road), Spearwood WA 6163	Spearwood	42	109	Cleaners Store & Toilet #2 - tile grout	10	N/A	Intact, not friable	No, if undisturbed	N/A	Testing conducted	Assumed the same as Staff Toilet Testing. Non suspected	No	Yes - BA7035/02 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liabile to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Eaves	80	YES	Damaged and deteriorating	Yes	LOW	Reseal or remove and replace with non ACM product. Keep vegetation away from panels to prevent ACM becoming friable.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Electrical switchboard & fuses	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Chimney Flue Lining	4	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Kitchen - vinyl flooring	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Toilet - vinyl tiles	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Shed - electrical switchboard & fuses	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Shed - carpet underlay	20	YES	Intact, not friable	Yes	MODERATE	Testing required. Remove in accordance with ACM removal requirements.	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Shed - cladding, partition fence & ridge capping	40	YES	Damaged and friable	Yes	HIGH	Remove and replace with non ACM product. Remove ACM ridge capping debris broken on the ground. Remove vegetation from all ACM products to prevent material being friable	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Shed - roofing	20	YES	Damaged and friable	Yes	HIGH	Remove and replace with non ACM product. Remove vegetation from all ACM products to prevent material being friable	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Fencing & ridge capping	15	YES	Damaged and friable	Yes	HIGH	Remove and replace with non ACM product. Remove vegetation from all ACM products to prevent material being friable	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Bathroom - tile grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
19/11/2019	Dwelling - 159 (Lot 260) Phoenix Road, Spearwood WA 6163	Spearwood	85	4453	Hallway cupboard - vinyl flooring	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Vinyl encapsulated underneath carpet. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	Coogee Community Centre, 19 Arlington Loop, Coogee WA 6166	Coogee	32	160	Electrical Switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
20/11/2019	South Coogee Agricultural Hall, 739 Rockingham Road, Munster WA 6166	Munster	29	159	Kitchen - sink, black tar resin underneath	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Some signs of deterioration otherwise mostly intact. Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	South Coogee Agricultural Hall, 739 Rockingham Road, Munster WA 6166	Munster	29	159	Kitchen - ceiling panels & bulkheads	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	South Coogee Agricultural Hall, 739 Rockingham Road, Munster WA 6166	Munster	29	159	Main Entrance - ceiling	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	South Coogee Agricultural Hall, 739 Rockingham Road, Munster WA 6166	Munster	29	159	Store Room - ceiling & clad walls	40	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	South Coogee Agricultural Hall, 739 Rockingham Road, Munster WA 6166	Munster	29	159	Store Room - sink, black tar resin underneath	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	South Coogee Agricultural Hall, 739 Rockingham Road, Munster WA 6166	Munster	29	159	Toilet Hallway - ceiling	6	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	South Coogee Agricultural Hall, 739 Rockingham Road, Munster WA 6166	Munster	29	159	Male Toilet - ceiling	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	South Coogee Agricultural Hall, 739 Rockingham Road, Munster WA 6166	Munster	29	159	Female Toilet - ceiling & batons	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	South Coogee Agricultural Hall, 739 Rockingham Road, Munster WA 6166	Munster	29	159	Slates to gable ends, front & rear	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		
20/11/2019	The Play Factory - Santich Park, Asquith Street (19 Beckett Close), Munster WA 6166	Munster	12	169	Toy Equipment Room - vinyl flooring	10	N/A	Intact, not friable	No, if undisturbed	N/A	Testing conducted	Non suspected	No	Yes - BA7154/02 - No Asbestos Detected	Yes	Katherine Kempin, Cale Bant		
20/11/2019	The Play Factory - Santich Park, Asquith Street (19 Beckett Close), Munster WA 6166	Munster	12	169	Kitchen - sink, black tar resin underneath	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Caution label implemented	Yes, before disturbed	No	Yes	Katherine Kempin, Cale Bant		

City of Cockburn Asbestos Register																		
Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liabile to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
18-Nov-19	Jean Willis House - Store, 249 Healy Road, Hamilton Hill WA 6163	Hamilton Hill	21	4393	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
18-Nov-19	Jean Willis House - Respite House, 249 Healy Road, Hamilton Hill WA 6163	Hamilton Hill	22	4394	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
18-Nov-19	Knowbarup Aboriginal Aged & Disabled Centre, 249 Healy Road, Hamilton Hill WA 6163	Hamilton Hill	23	4395	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
18-Nov-19	Disability Resource Centre, 1 Starling Street, Hamilton Hill WA 6163	Hamilton Hill	19	144	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
18-Nov-19	Changerooms - Len Packham, 96 Cordelia Avenue, Coolbellup WA 6163	Coolbellup	120	104	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
18-Nov-19	Coolbellup Community Centre, 90 Cordelia Avenue, Coolbellup WA 6163	Coolbellup	15	4357	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
18-Nov-19	Cockburn Tennis Club Toilets, 17A Recreation Road (11 Lucius Road), Hamilton Hill WA 6163	Hamilton Hill	46	2005	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
18-Nov-19	Bakers Square Changerooms, 1 Mortlock Street, Hamilton Hill WA 6163	Hamilton Hill	126	2023	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
19-Nov-19	Memorial Hall, 435 Carrington Street, Hamilton Hill WA 6163	Hamilton Hill	30	3254	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20-Nov-19	Port Coogee Toilet Block, 24 Medina Parade, Port Coogee WA 6163	North Coogee	83	4380	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20-Nov-19	Port Coogee Marina Services Office Building, 5 Maraboo Wharf, North Coogee WA 6163	North Coogee	84	4400	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20-Nov-19	Catherine Point Toilets, McTaggart Cove, North Coogee WA 6163	North Coogee	114	2000	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20-Nov-19	Picnic Shelters, 2110 Bennett Avenue, North Coogee WA 6163	North Coogee	133	174	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
19-Nov-19	Azelia Ley - Outside Toilet Homestead, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	N/A	BD000679	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Old Thunder Box Toilet, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	108	4397	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Manning Park North Toilet, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	N/A	BD000672	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Manning Park South Toilet, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	106	130	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Music Shell (Manning Park), Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	50	2180	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Old Wagon House Shed, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	87	2142	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
19-Nov-19	Azelia Ley - Old One Room Cottage, Azelia & Glenister Road, Hamilton Hill WA 6163	Hamilton Hill	89	4398	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
21-Nov-19	Depot - Rangers Office, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	53	154	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - Training Room, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	54	168	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - Administration Building, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	55	1681	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - Machinery Shed, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	56	1682	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - Dog Pound, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	57	1683	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liabile to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
21-Nov-19	Depot - Parks Department Building, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	58	1684	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - Wash Down Bay, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	59	1685	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - Signage Shed, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	60	1686	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - Environmental Storage Transportable, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	61	1687	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - Environmental Storage Shed, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	62	1688	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
21-Nov-19	Depot - Environmental Office, 54 Wellard Street, Bibra Lake WA 6163	Bibra Lake	63	1689	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Stephen Smith		
26-Nov-19	Bibra Lake Adventure Playground, North Lake Road WA 6163	Bibra Lake	146	187	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
26-Nov-19	Toilet Block East (Bibra Lake Adventure Park), Cnr Bibra Drive & Parkway, Bibra Lake WA 6163	Bibra Lake	110	2228	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
26-Nov-19	Scout Hall & Wetlands Nursery, 184 Hope Road, Bibra Lake WA 6163	Bibra Lake	76	2617	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
26-Nov-19	Changerooms - Meller Park, Hope Road, Bibra Lake WA 6163	Bibra Lake	115	1108	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
26-Nov-19	BMX Track Buildings & Transportable Toilets, Malabar Way, Bibra Lake WA 6163	Bibra Lake	90	1624	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
28-Nov-19	Beelilar Community Centre - East Beelilar, 33 Lakefront Avenue, Beelilar WA 6164	Beelilar	25	2304	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
28-Nov-19	Lakelands Hockey and Sporting Facility, South Lake Drive, South Lakes WA 6164	South Lake	156	?	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liabile to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
28-Nov-19	Jandakot Hall, 770 North Lake Road, South Lake WA 6164	South Lake	27	2025	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
28-Nov-19	Toilet Block (Jandakot Hall), 770 North Lake Road, South Lake WA 6164	South Lake	113	2026	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
28-Nov-19	Change Rooms - Anning Park, 770 North Lake Road, South Lake WA 6164	South Lake	125	141	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
28-Nov-19	Toilet Block - Hop Bush Park, Elderberry Drive, South Lake WA 6164	South Lake	104	138	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
28-Nov-19	Storage Building - Hop Bush Park, Elderberry Drive, South Lake WA 6164	South Lake	105	4396	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
28-Nov-19	Cockburn Bowling & Recreational Club, 40 Birchley Road, Yangebup WA 6164	Yangebup	103	4350	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
28/11/2019	Yangebup Clubrooms - Nicholson Reserve, 20 Swallow Drive, Yangebup WA 6164	Yangebup	131	2130	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
27-Nov-19	Harvest Lakes Community Centre, 62 Aurora Drive, Atwell WA 6164	Atwell	73	2270	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
27-Nov-19	Atwell Community Centre, 9 Lombe Gardens, Atwell WA 6164	Atwell	24	2230	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
27-Nov-19	Club Rooms Atwell Oval (Jandakot Jets Junior Football Club), Brencley Drive, Atwell WA 6164	Atwell	132	2219	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
27-Nov-19	Aubin Grove Sport & Community Facility, 71 Camden Boulevard, Aubin Grove WA 6164	Aubin Grove	78	4358	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
27-Nov-19	Banjup Community Hall, 41 Oxley Road, Banjup WA 6164	Banjup	33	2216	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
27-Nov-19	Jandakot Volunteer Bush Fire Brigade, Cnr Liddelow & Oxley Road, Banjup WA 6164	Banjup	2	164	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
22/11/2019	Transportable Toilets - 12 Poletti Road, Cockburn Central WA 6164	Cockburn Central	39	588	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liabile to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
27/11/2019	Cockburn Community Men's Shed, 2 Sullivan Street (Buckley Street), Cockburn Central WA 6164	Cockburn Central	80	4340	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
27/11/2019	Aquatic Recreation Centre (ARC), 31 Veterans Parade, Cockburn Central WA 6164	Cockburn Central	102	4449	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
27/11/2019	SES Headquarters (CVES), 71 Buckley Street, Cockburn Central WA 6164	Cockburn Central	4	4378	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
27/11/2019	Hammond Park/Botany Park Changerooms, 71 Macquarie Boulevard (Botany Parade) Hammond Park WA 6164	Hammond Park	79	4377	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
22/11/2019	Navel Base/Shacks - Female Toilet, 1136 Cockburn Road, Henderson WA 6166	Henderson	70	2017	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Picnic Shelter, 17 Turnbull Park Drive, Jandakot WA 6164	Jandakot	134	175	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Cockburn Youth Centre, 11-25 Wentworth Parade, Success WA 6164	Success	10	2308	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Success Regional Sport and Community Facility, 359 Hammond Road, Success WA 6164	Success	77	4355	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Cockburn Community Health Facility (Intergrated Health Building), Cnr 11 Wentworth Parade & Beellar Drive, Success WA 6164	Success	81	4381	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Weighbridge Office, 920 Rockingham Road, Wattleup WA 6166	Wattleup	91	171	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Workshop #1, 920 Rockingham Road, Wattleup WA 6166	Wattleup	92	190	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Workshop #2, 920 Rockingham Road, Wattleup WA 6166	Wattleup	93	191	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		



Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
20/11/2019	Henderson Waste Recovery Park - Workshop #3, 920 Rockingham Road, Wattleup WA 6166	Wattleup	94	192	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Toilet Block, 920 Rockingham Road, Wattleup WA 6166	Wattleup	95	4283	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Crib Room #1, 920 Rockingham Road, Wattleup WA 6166	Wattleup	96	4285	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Crib Room #2, 920 Rockingham Road, Wattleup WA 6166	Wattleup	97	4285(?)	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Site Office, 920 Rockingham Road, Wattleup WA 6166	Wattleup	98	4363	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Hazardous Chemical Shed, 920 Rockingham Road, Wattleup WA 6166	Wattleup	99	4364	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Transfer Station Building, 920 Rockingham Road, Wattleup WA 6166	Wattleup	100	4374	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Henderson Waste Recovery Park - Recycle Shop, 920 Rockingham Road, Wattleup WA 6166	Wattleup	101	4373	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
19/11/2019	Changerooms - Lucius Park Clubrooms, Hamilton Road, Spearwood WA 6163	Spearwood	128	122	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Ablution Block (Dubove Park) Cnr Freeth Road & Bohemia Street, Spearwood WA 6163	Spearwood	117	2043	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Watson Reserve Clubroom/Change Rooms, 342 Rockingham Road, Spearwood WA 6163	Spearwood	123	2019	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		

Date of Inspection	Address	Suburb	Property File LGIS Ref.	COC Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Site Works Attachment	Site Works Attachment
25/11/2019	Vacant Block (Cockburn bowling & Rec Club), 300 Rockingham Road, Spearwood WA 6163	Spearwood	6	134	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Coogee Beach Toilet Block, 4 Powell Road, Coogee WA 6166	Coogee	43	2011	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Coogee Café, 4 Powell Road, Coogee WA 6166	Coogee	74	2303	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Coogee Beach Lifesaving Club Inc., 4 Powell Road, Coogee WA 6166	Coogee	82	4379	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Jetty, Powell Road (11 Possner Way?), Coogee WA 6166	Coogee	44	2110	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	South Coogee Change Rooms, Russell Road West, Munster WA 6166	Munster	121	2032	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
20/11/2019	Santich Park Club Rooms, Asquith Street, Munster WA 6166	Munster	129	2126	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Cale Bant		
						0												
						0												
						0												
						0												
						0												
						0												
						0												
						0												
						0												
						0												
						0												

**City of Cockburn Asbestos Register of Works**

<b>Address</b>	<b>Property File Ref</b>	<b>ACM Location</b>	<b>ACM Presumed</b>	<b>ACM Condition</b>	<b>ACM Liable to damage or deterioration?</b>	<b>ACM Risk Level</b>	<b>Date</b>

<b>Contract or Name</b>	<b>Proposed Works</b>	<b>Training Provided</b>	<b>Code of Practice Provided</b>	<b>Sign Off Document Attachments</b>









































No  
Yes  
Yes, before disturbed

NO  
YES  
N/A

N/A  
Unknown  
Intact, not friable  
Damaged, not friable  
Damaged and deteriorating  
Damaged and friable  
Friable

Yes  
No, if undisturbed  
N/A

LOW  
MODERATE  
HIGH  
EXTREME  
N/A